

MISHAP REPORT

34th Support Battalion
CH47C S/N 70-15034
10 March 1981
Ft. Hood, Texas

Class B Aircraft Mishap

Aircraft was on a maintenance test flight. During an autorotation RPM check the pilot lowered the thrust to flat pitch and the rotor system exceeded 265 RPM before corrective action was initiated.

The maintenance section replaced the forward and aft rotor head and (1) one each forward and aft rotor blade and aircraft was released for flight.

R.G. Orr
R.G. ORR

RGO/ybn
P31-62
X2008